



[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

Overview for Complaint #:1675138 = RESOLVED

Complaint at: 109 EAST 9 STREET **BIN:** [1008963](#) **Borough:** MANHATTAN **ZIP:** 10003
Re: EMERGENCY WORK ORDER.MAIN BLDG W/WOOD JOIST&CRCKD 3RDFLHEADER W/INADEQUATE CONNECTION TO TRIMMER,WHICH WAS SUPPORTNG INTERIORWALL ADJ TO STAIRS.FLOORS SEVERELY SLOPNG TOWARDS CENTR STAIRS@2ND

Category Code: 73 FAILURE TO MAINTAIN

Assigned To: MANHATTAN CONSTRUCTION ENFORCEMENT **Priority:** C

Received: 08/15/2024 **Block:** 555 **Lot:** 40 **Community Board:** 103
Owner: 109E9 LLC

Last Inspection: 08/14/2024 - - BY BADGE # 9PNX
Disposition: 08/15/2024 - A1 - BUILDINGS VIOLATION(S) SERVED
DOB Violation #: 081424FEU10301PN
Comments: OWNR TO IMMED RTAIN NYSPE&LICENSED GC TO SHORE BLDG,AS REQD, UNDR FULL TIME CONT,NYSPE SUPERVISION/DIRECTION

Complaint Disposition History

#	Disposition Date	Code	Disposition	Inspection By	Date
---	------------------	------	-------------	---------------	------

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.