



[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

**Overview for Complaint #:1682501 = RESOLVED**

**Complaint at:** 109 EAST 9 STREET **BIN:** [1008963](#) **Borough:** MANHATTAN **ZIP:** 10003

Re: An unlicensed contractor did demolition work without a permit, when I asked one of the contractor they refused to identified them self are their company information. They didn't have the appropriate supervision or materials to protect the tenants while they were working. The license plate # to one of there vans is lfk6173.They worked from 10 AM to 5 PM on November 1st. It was only offered at the end of day after they were done.

**Category Code:** 7J WORK WITHOUT A PERMIT - OCCUPIED MULTIPLE DWELLING  
WORK WITHOUT A PERMIT - OCCUPIED MULTIPLE DWELLING : DEMOLITION

**Assigned To:** REAL TIME ENFORCEMENT **Priority:** A  
**311 Reference Number:** 311-20903170

**Received:** 11/22/2024 **Block:** 555 **Lot:** 40 **Community Board:** 103  
**Owner:** 109E9 LLC

**Last Inspection:** 11/22/2024 -- BY BADGE # 3260  
**Disposition:** 11/22/2024 - A8 - ECB VIOLATION SERVED  
**ECB Violation #:** 39131083H  
**Comments:** ATOI OBSERVED: 6 METAL SHOOTING INSTALLED AT 1ST FLOOR AND REINFORCING BEAMS WITH WOOD SUPPORTING THE APTS ABOVE USING TO FIX STRUCTURE DEFECT WITHOUT DOB PERMIT. ECB VIOLATION ISSUED.

**Complaint Disposition History**

#	Disposition Date	Disposition Code	Disposition	Inspection By	Date
---	------------------	------------------	-------------	---------------	------

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.