



[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

Overview for Complaint #:1691101 = ACTIVE

Complaint at: 109 EAST 9 STREET

BIN: [1008963](#)

Borough: MANHATTAN **ZIP:** 10003

Re: no permit displayed. Power tools being used in an areacovered; sheetrock and drills heard being used. aim to disguise formerwork without a permit.

Category Code: 7J WORK WITHOUT A PERMIT - OCCUPIED MULTIPLE DWELLING
WORK WITHOUT A PERMIT - OCCUPIED MULTIPLE DWELLING : CONSTRUCTION

Assigned To: REAL TIME ENFORCEMENT

Priority: A

311 Reference Number: 311-22276352

Received: 03/17/2025

Block: 555

Lot: 40

Community Board: 103

Owner: 109E9 LLC

Last Inspection: 03/17/2025 - - BY BADGE # 3625

Disposition: 03/17/2025 - C3 - ACCESS DENIED - 1ST ATTEMPT

Comments: ATOI ACCESS DENIED BY MALE COMING OUT FROM FRONT DOOR OF RESIDENTIAL ENTRANCE. KNOCKED ON DOOR, ANNOUNCED MYSELF AND HE SAID NO AND WALKED AWAY. LS4 POSTED AT BUILDING FRONT.

Complaint Disposition History

| # | Disposition Date Code | Disposition | Inspection By | Date |
|---|--------------------------|-------------|------------------|------|
|---|--------------------------|-------------|------------------|------|

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.