



[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

Overview for Complaint #:1694293 = RESOLVED

Complaint at: 109 EAST 9 STREET **BIN:** 1008963 **Borough:** MANHATTAN **ZIP:** 10003

Re: The building owner removed the stop work order notices posted by the building department and is attempting to continue illegal construction while the building is occupied. Please dispatch inspectors to halt the unauthorized work.

Category Code: 7J WORK WITHOUT A PERMIT - OCCUPIED MULTIPLE DWELLING
 WORK WITHOUT A PERMIT - OCCUPIED MULTIPLE DWELLING : CONSTRUCTION

Assigned To: REAL TIME ENFORCEMENT **Priority:** A
311 Reference Number: 311-22730251

Received: 04/28/2025 **Block:** 555 **Lot:** 40 **Community Board:** 103
Owner: 109E9 LLC

Last Inspection: 04/28/2025 - - BY BADGE # 3679
Disposition: 04/29/2025 - I2 - NO VIOLATION WARRANTED FOR COMPLAINT AT TIME OF INSPECTION
Comments: OBSERVED STOP WORK ORDER ON THE FRONT DOOR AT TIME OF INSPECTION, DID NOT OBSERVED ANY CONSTRUCTION ACTIVITY GOING AGAINST A STOP WORK ORDER FOR THE SCOPE OF WORK UNDER JOB #M01181265-I1

Complaint Disposition History

#	Disposition Date	Code	Disposition	Inspection By	Date
---	------------------	------	-------------	---------------	------

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.